



P.S:1.The attention please,if panel is the CMO or TOSHIBA.
The panel-bk right side need rubber washer 1mm.

D	AD/BOARD	2023L/2023-9906		MODEL		PART NAME				Assembly			
	INVERTER	TIP017WS-01											
	KEY PAD	PCBKEY019A0		PART NO.		APPROVED		DRAWN		JACK		REV.	
	PANEL:	AU-G121SN01 CMO-N121X5-L01 CMO-G121X1-L01 SHARP-LQ121S1DG61_SP_012706 TOSHIBA-LTD121LA#SG										MATERIAL	SECC
	1	2	3	4	5								